

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: ✓  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? No change measurement were  
taken with the transit level & tiltmeter.

Inspected By: Jeremy Gross & Brian Ogle  
Date: 7/8/2013

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: ✓  
Stringers: N/A  
Girders (Conc./Steel): ✓  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: ✓  
Wingwalls: N/A  
Footings: ✓  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

No change noted during visual  
inspection. Measurements were taken with transit level and  
tilt meter.

Inspected By: Steven Houze & Jereme Grass  
Date: 2-1-13

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: ✓  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: ✓  
Wingwalls: N/A  
Footings: ✓  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

Measurements taken with transit  
level & tiltmeter. No change per visual inspection.

Inspected By: Stacy Houze & Jerene Grass

Date: 1/25/2013

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ☒  
Roadway: ☒  
Deck: ☒  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ☒  
Caps/Piers: ☒  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ☒  
Embankment (Scour): ☒  
Conc. Spall/Cracks: ☒

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Measurements taken with tilt meter  
and transit level, no changes noted during visual inspection.

Inspected By: Steven Houe & Jerome Grass  
Date: 1-18-2013

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? No changes. Measurements  
were taken with the tilt-a-meter, and the  
level was used to shoot grade.

Inspected By: Jerome Gross & Steven Howze  
Date: 1-11-2013

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

No changes. Measurements  
were taken with the tilt-meter, and the  
level was used to spot grade.

Inspected By:

Jeremie Grass & Steven Hawze

Date:

1-11-2013

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? No changes. Measurements were taken  
with filto-meter + transit level. Visual inspection was performed.

Inspected By: Steven Howie + Jerome Grass  
Date: 12/28/12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

Tilt meter was used. Elevations  
were taken on both sides of structure at each bent. Visual  
inspection was performed.

Inspected By: Steven Houze & Terene Grass

Date: 12/21/12



## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

Tilt O meter was used on structure,  
readings were recorded into database. Elevation readings  
were taken on both sides of the structure. No  
change was noted upon this visual inspection.

Inspected By: Jerome M. Grass & Steven Hawze  
Date: 12/14/2012

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ☒  
Roadway: ☒  
Deck: ☒  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ☒  
Caps/Piers: ☒  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ☒  
Embankment (Scour): ☒  
Conc. Spall/Cracks: ☐

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or ☒ NO

Any changes noted? If so what?

Tilt o meter was used on structure, readings  
were recorded into data base. Elevation readings were taken on both sides  
of structure. No change was noted upon this visual inspection.

Inspected By: Steven Howze & Brian Ogle  
Date: 12/7/12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks:           

✓ - if element of structure was inspected

N/A - if element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

TILT O METER WAS USED ON STRUCTURE,  
READINGS WERE RECORDED INTO DATA BASE. NO CHANGE WAS NOTED UPON  
THIS VISUAL INSPECTION.

Inspected By: STEVEN HOWZE & BRIAN OGLE

Date: 11/30/12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks:           

✓ - if element of structure was inspected

N/A - if element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Elevation readings were taken on both sides  
of structure. The largest difference noted was 0.04

Inspected By: Steven Howze & Brian Ogle

Date: 11/21/12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour):             
Conc. Spall/Cracks:           

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Elevation readings were taken on  
both sides of the structure. 0.04 was the largest difference  
that was noted.

Inspected By: Brian Ogle, Jereme Grass, Steven Howze  
Date: 11/16/12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: ✓  
Wingwalls: ✓  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? NO Change, there was less  
than .02" change from previous elevation reading

Inspected By: Ryan Byrd + Steven Houze  
Date: 11-9-12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ☒  
Roadway: ☒  
Deck: ☒  
Bearings: ☒  
Stringers: ☒  
Girders (Conc./Steel): ☒  
Piling: ☒  
Caps/Piers: ☒  
Backwalls: ☒  
Wingwalls: ☒  
Footings: ☒  
Waterway: ☒  
Embankment (Scour): ☒  
Conc. Spall/Cracks: ☒

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

No changes. There was less  
than a 0.01" reading difference from August 30 except at  
bent #3 on left side of structure which was 0.04". This has  
been typical since beginning.

Inspected By:

Steven Howe + Ben Bluschi

Date:

11-2-12

## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
 Str. # 61042320104941 Recall # 051450 Route: LA 70  
 Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
 Roadway: ✓  
 Deck: ✓  
 Bearings: N/A  
 Stringers: N/A  
 Girders (Conc./Steel): N/A  
 Piling: ✓  
 Caps/Piers: ✓  
 Backwalls: ✓  
 Wingwalls: ✓  
 Footings: N/A  
 Waterway: ✓  
 Embankment (Scour): ✓  
 Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Bridge elevations were taken on  
both sides of the structure at each bent. There was less  
than a 0.01" reading difference from Aug 30 except at bent #3 on  
left side was a 0.05" difference. A visual inspection was performed.  
No evidence of bridge settlement noted.

Inspected By: Steven Howze + Ben Bluschi  
 Date: 10/26/12



## WEEKLY CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: ✓  
Wingwalls: ✓  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what?

Bridge elevations were taken on  
both sides of structure. Visual inspection was performed.  
No evidence of bridge settling.

Inspected By: Steven Hure & Brian Ogle

Date: 10/19/12